



1) Openers must fit within the dimensions on the highlighted box of the diagram (dimensioned from the bottom bolt hole of the shankholder).

2) Opener sweeps or shovels should not be any wider than 4.5" (115mm) total width.

Openers that do not fit within the specified dimensions may compromise the trip out height and clearance with the packer wheel which could lead to damage to the openers and loss of warranty coverage.

MORRIS INDUSTRIES
 AUGUST 2018
 RESEARCH & DEVELOPMENT